

9/16-18 Port on Top
for Pressure Gage

Fill Cap

3 1/2

Output Port
3/4 16 Str. Thread

12 3/4

3 1/2

13 3/4

Return Port
3/4-16 Str. Thread

11 7/8

13 7/8

20 5/8

11 1/2

